





SHAFT SHOWN IN START POSITION




TERMIANL DETAIL



NUT 1PC



WASHER 1PC



P. C. B MOUNTING HOLES

START POSITION

CODE

C. W —

1: ON
0: OFF

TERM	POS	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
①		0	0	1	1	0	0	1	1	0	0	1	1	0	0	1	1
②		0	0	0	1	1	1	1	0	0	0	0	1	1	1	1	0
③		1	1	1	1	1	0	0	0	0	0	0	0	0	1	1	1
④		1	0	0	0	0	0	0	0	0	1	1	1	1	1	1	1

GRAY code
ES 1612

	L	F
	15.0	7.0
	20.0	12.0

